FREE SAMPLE

The opening pages of

1964 Triumph Bonneville Buyer's Guide

Read these pages exactly as they appear in the full guide.
Nothing here is rewritten or summarised — it is the product itself,
so you can judge the depth before you spend a dollar.

The full guide: https://ironheadguides.com/product/IH-TRIUMPH-BONNEVILLE-1964

IronHead — instant PDF download after checkout.

IRONHEAD

1964 T120 Bonneville

Factory-Correct Restoration Guide

KEY FACTS AT A GLANCE

- **Model year covered:** 1964 only (T120 Bonneville; T120R in the US). The year 12-volt electrics arrived. This guide does not cover the 1963 or 1965 T120 except where differences are explicitly noted.
- **Engine:** 649 cc air-cooled OHV parallel twin; 71.0 mm x 82.0 mm bore x stroke; unit construction with 4-speed gearbox.
- **Fuel system:** Twin Amal Monobloc carburetors.
- **Ignition:** Battery-and-coil breaker-point ignition.
- **Electrics:** 12-VOLT — new for 1964 (Hagerty). The single biggest electrical change in the unit-650's early life.
- **Transmission:** 4-speed constant-mesh, in unit; chain primary; wet multi-plate clutch; chain final drive.
- **Brakes:** Drum brakes front and rear.
- **Wheels/tires:** Wire-spoked wheels; 3.25 x 19 front, 3.50 x 18 rear (period fitment).
- **Frame/engine serials:** DU5825 through DU13374 (7,550 numbers allocated). Engine number on the left crankcase below the barrel; engine and frame numbers should match.
- **Power:** Approx. 46 bhp (period road-test figure for the unit 650).
- **Production context:** DU5825-DU13374 bounds the model-year run.
- **Key 1964-only features:** 12-volt electrics (new); the last full year of the early unit-650 specification before the mid-60s refinements.

SAMPLE EXCERPT — full guide available at the link on the cover sheet

This is a single-year guide. It covers the 1964 Triumph T120 Bonneville only. Other model years are discussed solely to mark differences — for a different year, use that year's IronHead guide.

1. Manufacturer history: Triumph

Triumph began as a bicycle and motorcycle maker in Coventry, England, founded by the German immigrant Siegfried Bettmann in the 1880s; the company built its first motorcycle in 1902. Through the 1920s Triumph was one of Britain's major motorcycle manufacturers, and in 1936 the arrival of designer Edward Turner changed the company's trajectory permanently: his 1937/38 Speed Twin — a 500 cc parallel twin — created the template (light, narrow, good-looking twin with real performance) that the whole British industry, and then the Japanese, would chase for the next forty years.

Bombing forced the move from Coventry to a new factory at Meriden in 1942, and in 1951 Triumph was sold to the BSA group. The 1950s and 1960s were the boom years: the 650 twins (Thunderbird, Tiger, Bonneville) sold in huge numbers, overwhelmingly to the United States — more than 65 percent of Bonneville production went to America, a figure Hagerty's marque history repeats across its model summaries. The American market's appetite for the big parallel twin is the reason the Bonneville exists in the form it does: tuned for US tastes, styled for US showrooms, and sold through legendary importers like Johnson Motors (JoMo) on the West Coast and the Triumph Corporation (TriCor) in the East.

The 1970s brought the collapse. Mismanagement, labor strife, and Japanese competition pushed BSA/Triumph to the brink; the 1973 creation of Norton Villiers Triumph (NVT) was followed by an 18-month workers' sit-in at Meriden (Hagerty), after which the factory continued as the Meriden Workers' Co-operative — owner-workers building essentially the same motorcycles with almost no development money. Production limped on until 1983, when the Meriden works closed and the rest of Triumph's motorcycle production ended with it. Businessman John Bloor bought the name and assets the same year; his new Hinckley company would eventually relaunch the Bonneville in 2001, but the Meriden-built line this guide covers died in 1983.

For the restorer, that history explains the parts landscape: enormous US sales mean used parts and pattern parts are plentiful for the popular years; the co-operative years (1975-1983) mean running changes, mixed fittings, and documentation gaps that demand verification against the factory parts books rather than memory.

2. Model history: the Bonneville

The Bonneville began in 1959 as the T120: a 650 cc pre-unit parallel twin, essentially a twin-carburettor Tiger 110, named for the land-speed records Johnny Allen set on the Bonneville Salt Flats in 1956 aboard a Triumph-powered streamliner. It was an instant hit in America, and for the next two decades the Bonneville was Triumph's flagship — the bike the company was known by.

Three mechanical generations matter for the restorer. The **pre-unit T120** (1959-1962) has a separate gearbox. The **unit 650** (1963-1972, covered by factory workshop manual 99-0883/0889 for 1963-1970) combines engine and gearbox in one crankcase casting — the engine most people picture when they hear "Bonneville." The **750 T140** (1973-1983) is a bored-and-developed descendant of the oil-in-frame 650, covered by the T140 factory repair manual. Within those generations, the year-to-year changes — carburetors, brakes, frames, electrics, shift side, paint — are exactly what this guide series isolates, one year at a time.

Two production facts anchor every guide in this series. First, Hagerty's marque history records that by the time the last 649 cc T120 was sold in 1972, production had reached **250,000 units** — the Bonneville was a mass-market machine, not an exotic. Second, the same source puts total T140 production at roughly **60,000 units** across 1973-1983. And more than 65 percent of all Bonneville production was sold in the United States, which is why US-specification details (US-only paint names, US-market fittings, the T120R designation for the US road model) dominate the restoration record.

SAMPLE EXCERPT — full guide available at the link on the cover sheet

Designation	Years	What changed that matters
T120 Bonneville	1959-1962	650 cc pre-unit twin. Named for the 1956 Bonneville Salt Flats land-speed records.
T120 Bonneville (unit)	1963-1970	Unit construction (engine and gearbox in one casting) from 1963. 12-volt electrics from 1964. Amal Concentric carbs and 8-inch twin-leading-shoe front brake from 1968.
T120R/T120V (oil-in-frame)	1971-1972	Oil carried in the frame instead of a separate tank. 54 bhp @ 6,750 rpm. Five-speed option for 1972. Last of the 649 cc line: ~250,000 T120s built in total (Hagerty).
T140V Bonneville	1973-1978	750 twin (724 cc at launch, 744 cc shortly after). Five-speed, right-side shift to 1975, left-side shift and rear disc from 1976.
T140J Silver Jubilee	1977	Limited edition: 1,000 UK + 1,000 US machines (Bonhams).
T140E / T140D	1979-1980	E for emissions: parallel-port head, Amal MkII carbs, Lucas Rita electronic ignition. D Special: factory custom by Tom Higham.
T140ES Electro	1980-1983	Electric start alongside the kick starter.
T140LE Royal Wedding	1981	Limited edition for the Charles and Diana wedding; published build totals conflict (see Section 10).
T140AV	1981-1983	Anti-vibration rubber-mounted police/touring model.
T140 TSS / TSX	1982-1983	Eight-valve Weslake-derived head on the TSS (~60 bhp per Hagerty).
End of line	1983	Meriden closes. ~60,000 T140s built in total (Hagerty).

3. What makes the 1964 T120 Bonneville unique

The 1964 T120 is the 12-volt year — the single most practical change Triumph made to the early unit Bonneville. Hagerty's marque history records that 12-volt electrics arrived in 1964, ending the 6-volt era that closed with the 1963 model. Everything else about the 1964 bike is continuous with 1963: the unit-construction 649 twin, twin Amal Monoblocs, 4-speed gearbox, and drum brakes.

1964-only details:

- **12-volt electrics.** Battery, coil, rectifier, bulbs, and horn are all

12-volt items. This is the fastest authenticity check separating a 1964 from a 1963: a "1964" with 6-volt components is either a re-stamped 1963 or a bike assembled from mixed-year parts. Conversely, a 1963 converted to 12 volts is a modified bike, not a factory 1964.

- **Carryover everything else.** The cases, cycle parts, and trim are

1963-continuous. Do not expect — or fit — 1965-on refinements.

- **Monoblocs continue.** The Amal Concentric is still four years away

(1968). Monoblocs are correct for 1964.

1964 buyer cautions:

- **The 6-volt/12-volt boundary is the whole game.** Verify the electrical

SAMPLE EXCERPT — full guide available at the link on the cover sheet

system voltage against the serial number: DU5825-DU13374 should be 12-volt throughout. Mixed-voltage bikes (6-volt parts on a 1964 frame, or vice versa) signal a parts-bin assembly.

- **Number-range discipline.** The 1964 allocation (DU5825-DU13374) sits

directly between 1963 and 1965 with no gaps and no overlaps in the published ranges — a clean check. Frame and engine numbers should match (Lowbrow Customs).

4. Decoding your 1964 Bonneville

The 1964 allocation ran from **DU5825** through **DU13374** — 7,550 numbers (Lowbrow Customs). Engine number location: left crankcase below the cylinder barrel. Frame number: steering head. The two should match on an original bike, and both must fall inside DU5825-DU13374 for a genuine

1964. As with all years in this series, allocations bound the run but are

not published built totals.

5. Engine — technical restoration data

The table below is the 1964 T120 Bonneville's technical core. Every figure is sourced; where no verified factory figure was found in the sources checked, the table says so explicitly rather than printing a plausible number. Use the factory workshop manual for your exact model as the final authority.

Specification	Detail
Engine	649 cc air-cooled OHV parallel twin, unit construction
Bore x stroke	71.0 mm x 82.0 mm
Compression ratio	Not printed: no verified factory figure found in the sources checked.
Carburetion	Twin Amal Monobloc
Ignition	Battery-and-coil, breaker points
Power	Approx. 46 bhp (period road-test figure for the unit 650)
Gearbox	4-speed constant-mesh, in unit with engine
Clutch / primary	Wet multi-plate clutch; chain primary drive
Final drive	Chain
Frame	Steel cradle, unit-650 type
Front suspension	Telescopic fork
Rear suspension	Twin Girling shock absorbers
Front brake	Drum
Rear brake	Drum
Wheels	Wire-spoked, steel rims
Tires (period)	3.25 x 19 front, 3.50 x 18 rear
Electrics	12-volt (NEW for 1964)
Fuel capacity	Not printed: verify against the factory parts book for the year.

SAMPLE EXCERPT — full guide available at the link on the cover sheet

6. Transmission, clutch and primary drive

The 1964 runs a 4-speed constant-mesh, in unit with engine. Wet multi-plate clutch; chain primary drive. Final drive is by Chain. Rebuild practice is standard unit-twin work: inspect gear dogs and slots for rounding, replace bearings and seals as a set, check clutch-plate flatness and basket notching, and set the primary-chain tension and clutch adjustment to the factory manual before judging gearbox behavior.

7. Frame, suspension, wheels and brakes

Frame: Steel cradle, unit-650 type. Front suspension: Telescopic fork. Rear: Twin Girling shock absorbers. Brakes: Drum front, Drum rear. Wheels: Wire-spoked, steel rims. Wheel and brake originality is checked as a set — hub, brake plate or caliper, and fork fitment must all agree with the year's specification in Section 3.

8. Electrics, ignition and instruments

Ignition: Battery-and-coil, breaker points. Carburetion: Twin Amal Monobloc. Electrics: 12-volt (NEW for 1964). Fit a new wiring harness — original insulation is finished — rebuild or replace the switches, fit the correct battery, and test the charging system under load. Set timing to the factory manual before attempting any carburetion tuning.

9. Paint, trim and finishes

No factory-verified 1964 color palette was found in the sources checked for this guide. The factory's paint-formula discipline is documented (service bulletin T-63-48, June 1963, via the Vintage Triumph Register), but a year-verified 1964 palette was not. Verify against the factory parts book and a period 1964 brochure before paint — this guide prints no palette rather than a dubious one.

10. Production and rarity

No published model-year production split was found in the sources checked. The verifiable bound is the allocation **DU5825 through DU13374** (7,550 numbers). Context: total T120 production reached 250,000 units by 1972 (Hagerty).

11. Corrosion and wear areas to inspect

Check every one of these before committing to the restoration — they are the places 1964 Bonnevilles hide their expensive surprises.

- **Chrome (mudguards, rims):** thin original plating; expect rechroming, not polishing.
- **Exhaust:** rots from the inside; check silencers and pipe seams.
- **Frame tubes:** rust where paint has failed, especially the lower rails.
- **Tank interior:** borescope before paint.
- **Electrical connections:** the new 12-volt system is more tolerant than 6-volt, but 60-year-old bullet connectors still need replacement.
- **Fasteners:** original plating gone; corrosion cosmetic but pervasive.

12. Restoration sequence

Work in an order that never forces you to undo finished work. The sequence below is the standard professional order for a unit-twin Triumph; the notes flag where the 1964 T120 Bonneville needs special attention.

1. **Document everything first.** Photograph the complete bike from all sides,

SAMPLE EXCERPT — full guide available at the link on the cover sheet

then every assembly before you touch a fastener. Record the frame and engine numbers (see Section 4) and check them against the year ranges before spending money — a mis-described year is the most expensive restoration mistake.

2. **Assess, don't strip.** Inventory what's original, what's period-correct,

what's wrong-year, and what's missing. On a 1964, pay particular attention to the 12-volt electrical system and its originality.

3. **Engine and gearbox out; frame inspection.** Check the frame for crash

damage, cracks at the steering head and swingarm pivot, and previous repairs. Standard unit-650 frame checks: steering head, swingarm pivot, lower rails.

4. **Engine rebuild.** Split only as far as needed. Measure everything:

bore, crank journals, cam bushings, valve guides. Rebores on these barrels are routine, but match pistons to the measured clearance, not to the catalogue's optimism. Replace the sludge-trap plug's staking on the crank — a loose sludge trap destroys cranks.

5. **Gearbox and clutch.** Inspect dogs and slots for rounding, replace

bearings and seals as a set, check clutch-plate flatness and basket notching.

6. **Cycle parts.** Rebuild forks with new seals and correct oil; rebuild

shocks or replace with correct-pattern units. Wheel rebuilds: new spokes and nipples, rims trued — chrome rims that are pitted will not take a lasting polish.

7. **Brakes.** Drum brakes front and rear: new shoes arced to the drums, drum surfaces checked for scoring/ovality, new cables. Rebuild hydraulics completely on disc models:

seals, hoses (replace, don't reuse), master-cylinder bore inspection.

8. **Electrics.** New wiring harness (the original insulation is done),

rebuilt or replaced switches, correct battery, charging-system test under load. Verify the whole system is 12-volt and consistent — battery, coil, rectifier, bulbs, horn. Mixed-voltage parts indicate a parts-bin bike.

9. **Paint and plating.** Paint last among the major jobs, after all

trial-fitting is done. Do not paint until the color is verified against the factory parts book or a period 1964 brochure.

10. **Final assembly and shakedown.** Torque to the factory manual's figures

(see Section 13), set timing and carburation to the book, then run a disciplined shakedown: heat cycles, re-torque the head, re-check tappets, change the oil early.

13. Torque values and service data

Torque figures are **not printed here from memory**. Triumph revised fastener specifications across the run, and a wrong figure on a cylinder-head stud or a brake caliper is how threads and castings get destroyed. Use the factory workshop manual for your exact model:

- **1963-1970 650 twins:** Triumph factory workshop manual 99-0883/0889

(unit-construction 650 cc models, 1963-1970), which keys running changes to engine-number breakpoints.

- **1971-1972 oil-in-frame 650s:** the factory manual covering the

oil-bearing-frame models.

- **1973-1983 750s:** the Triumph T140 factory repair manual (covers

T140V/RV/J/E/D/ES/AV/LE/W/EX/TSS/TSX, 1973-1988).

- **General procedures and second opinions:** Haynes Owners Workshop Manual

SAMPLE EXCERPT — full guide available at the link on the cover sheet